

# 2008 SBT Replacement Core Charges \*

This list is provided as a guideline to our customers for items that are often damaged or missing from their core.  
Additional charges may apply not listed below, such as missing bolts and other items specific to certain engines.

## Sea-Doo

Engine	Case	Cylinder	Crankshaft	Head	Head Cover
587	\$695	\$350	ea	\$200	\$165 \$70
657	\$695	\$350	ea	\$200	\$165 \$70
717	\$695	\$350	ea	\$200	\$165 \$70
787 & 787 RFI	\$750	\$425	ea	\$200	\$165 \$70
951	\$875	\$405		\$200	\$235 N/A
951 DI	\$1,155	\$831		\$200	\$441 N/A
4-Stroke	\$995			\$200	\$200 N/A

## Yamaha

Engine	Case	Cylinder	Crankshaft	Head	Head Cover
500	\$595	N/A	\$200	\$85	N/A
650	\$500	\$260	\$200	\$90	N/A
701T & 701S	\$310	\$275	\$200	\$165	N/A
701X	\$480	\$295	\$200	\$135	N/A
760	\$360	\$400	\$200	\$175	N/A
800	\$280	\$350	ea	\$200	\$145 N/A
1100	\$500	\$675	\$200	\$125	\$80
1200	\$500	\$800	\$200	\$125	\$80
1200 PV	\$515	\$365	ea	\$200	\$205 \$90
1300	\$670	\$770	ea	\$200	\$340 N/A
4-Stroke	\$995		\$200	\$200	\$100

## Kawasaki

Engine	Case	Cylinder	Crankshaft	Head	Head Cover
440	\$250	\$310	\$200	\$115	N/A
550	\$250	\$310	\$200	\$115	N/A
650	\$345	\$445	\$200	\$140	N/A
750	\$250	\$460	\$200	\$155	N/A
900	\$360	\$620	\$200	\$215	N/A
1100	\$305	\$635	\$200	\$220	N/A
1100 DI	\$440	\$660	\$200	\$240	N/A
1200	\$420	\$360	ea	\$200	\$100 ea N/A

## Polaris

Engine	Case	Cylinder	Crankshaft	Head	Head Cover
650	\$650	\$312	ea	\$200	\$114 ea N/A
700	\$400	\$295	ea	\$200	\$75 ea \$40 ea
750	\$650	\$350	ea	\$200	\$114 ea N/A
777	\$400	\$325	ea	\$200	\$75 ea \$40 ea
777 DI	\$400	\$325	ea	\$200	\$190 ea \$40 ea
780	\$650	\$410	ea	\$200	\$114 ea N/A
900	\$450	\$300	ea	\$200	\$75 ea \$40 ea
1050	\$450	\$300	ea	\$200	\$75 ea \$40 ea
1200	\$550	\$325	ea	\$200	\$75 ea \$40 ea
1200 DI	\$550	\$370	ea	\$200	\$190 ea N/A

## Tigershark

Engine	Case	Cylinder	Crankshaft	Head	Head Cover
640	\$515	\$555	\$200	\$175	N/A
770	\$770	\$675	\$200	\$195	N/A
900	\$970	\$315	ea	\$200	\$80 ea N/A
1000	\$945	\$315	ea	\$200	\$80 ea N/A

<b>RAVE Valves</b>	\$150	ea
<b>Power Valves</b>	\$120	ea
<b>Counter Balance Shaft</b>	\$150	

\* Replacement Core Charges apply to any component received by SBT that is missing, modified, or damaged beyond reasonable repair.